•	Work for Property Loc		5220 North 29th Street	
Date:	<b>Property is:</b> Single Fan 8/30/2010	nily X Duple	x Other	
	-		The City of Milway less the Dedougles and Avenue	de site a sur data in sur sur sur dations
take no respo	onsibility for problems discovered a	after the inspection da	<ul> <li>The City of Milwaukee, the Redevelopment Aute, or for omissions through error or oversight. The deral Block Grant or HOME programs.</li> </ul>	
Exterior (	Condition Report			
Location	Required Work		Note/Comments	Cost
Site	Landscaping	n/a   X   Yes	Self Help	\$
	Steps/Handrails	n/a   X   Yes		\$
	Service walks	n/a X Yes		\$
	Fencing	n/a X Yes		\$
	Parking	n/a X Yes		\$
	Retaining walls	n/a X Yes	]	\$
	Other	n/a X Yes	]	\$
C	Other	n/a X Yes	]	\$
Garage	Shingles: repair	n/a X Yes	]	\$
	Shingles: Roof over existing	n/a X Yes	]	\$
	Shingles:Tear off & re-roof	n/a Yes X	Tear off and replace shingles	\$ 1,750.00
	Gutters/downspouts	n/a X Yes	]	\$
	Flashing	n/a X Yes	 ]	\$
	Eaves	n/a X Yes	]	\$
	Siding	n/a X Yes	]	\$
	Doors	n/a Yes X	Replace overhead door	\$ 950.00
	Windows	n/a X Yes	1	\$
	Slab	n/a X Yes	1	\$
	Paint	n/a Yes X	Wood siding peeling paint	\$ 900.00
	Electrical	n/a X Yes	7	\$
	Other	n/a Yes X	Overhang needs rebuilding	\$ 750.00
Porches	Roof	n/a X Yes	]	\$
	Deck-upper	n/a X Yes	]	\$
	Decklower	n/a X Yes	1	\$
	Steps/handrails	n/a X Yes	]	\$
	Ceiling	n/a X Yes		\$
	Guardrails	n/a X Yes	<del>-</del> ]	\$
	Structural	n/a X Yes	<u>-</u> ]	\$
	Paint	n/a X Yes	7	\$

n/a Yes

Other

\$

## House

Chimney	n/a X Yes	\$
Shingles: repair	n/a X Yes	\$
Shingles: Roof over existing	n/a X Yes	\$
Shingles:Tear off & re-roof	n/a X Yes	\$
Gutters/downspouts	n/a X Yes	\$
Flashing	n/a X Yes	\$
Eaves	n/a X Yes	\$
Siding	n/a X Yes	\$
Storm Doors	n/a X Yes	\$
Prime ("main") Doors	n/a X Yes	\$
Storm Windows	n/a X Yes	\$
Prime ("main") Windows	n/a X Yes	\$
Paint	n/a X Yes	\$
Foundation	n/a X Yes	\$
Electrical	n/a X Yes	\$
Other	n/a Yes	\$
Other	n/a Yes	\$
Other	n/a Yes	\$
Other	n/a Yes	\$

Exterior: Estimated Cost:\* \$
\*average contracted cost. Actual costs may vary. Self help will reduce the amount.

4,350.00

Interior Co	ondition Report				_	
	( 3 ),	X			Lower unit of duplex	
Mechanical	Upper unit of duplex Required Work				Other	
Heating	Roquirou Work					
	Repair/replace boiler	n/a X	Υe	s	]	\$ 
	Repair radiation	n/a X	Υe	s	]	\$ 
	Repair/replace furnace	n/a	Υe	s X	Replace furnace	\$ 4,000.00
	Repair ductwork	n/a X	Υe	s	]	\$
	Replace thermostat	n/a X	Υe	s	]	\$
	Repair/replace grilles	n/a X	Υe	s	]	\$ 
Electrical	Tune boiler/furn. insp ht exchang	j∉n/a X	Υe	s	]	\$ 
Electrical	Repair/replace receptacles	n/a X	Υe	s	]	\$ 
	Repair/replace switches	n/a X	Υe	s		\$
	Repair/replace fixtures	n/a	Υe	s X	Several new needed	\$ 250.00
	Install outlets and circuits	n/a X	Υe	s	]	\$
	Install outlets and circuits	n/a X	Υe	s	]	\$
	Install outlets and circuits	n/a X	Υe	s	]	\$
	Install outlets and circuits	n/a X	Υe	s	]	\$
	Upgrade service	n/a X	Υe	s	]	\$
	Other	n/a	Υe	s	]	\$
	Other	n/a	Υe	s	]	\$
Plumbing	Repair/replace kitchen sink	n/a X	Ye	s [	1	\$
	Repair/replace kitchen sink fauce	ein/a X	Υe	s [	]	\$
	Repair/replace tub	n/a X			]	\$
	Repair/replace tub faucet	n/a X		s [	1	\$
	Repair/replace toilet	n/a X		s	1	\$
	Repair/replace lavatory	n/a X		s	1	\$
	Repair/replace lavatory faucet	n/a X			1	\$
	Repair/replace wash tub	n/a X			]	\$
	Repair/replace wash tub faucet	n/a X			]	\$
	Unclog piping:	n/a X		s		\$
	Repair drain/waste/vent piping	n/a X	Υe	s	]	\$
	Repair water piping	n/a X			]	\$
	Repair/replace water heater	n/a		s X	Replace water heater	\$ 650.00
	Other	n/a	Υe	s	]	\$

\$

n/a Yes

Other

Replace broken glass   n/a   Yes   X   Several cracked glass   S	250.00	ф	Covered exacts of place		n/n 🖂	Danlaga hvalvan alaga	Windows
Doors         Repair or replace doors         n/a         Yes         X         Several new needed         \$           Repair or repl. locks/latches         n/a         X         Yes         Self Help         \$           Walls/Ceilings             Repair or repl. @ defective             n/a             X             Yes             Self Help             \$               Paint               Repair or repl. @ defective             n/a             Yes             X             Several rooms need fresh paint             \$               Fire Safety               Install smoke alarm: bsmt.             n/a             Yes             X             Self Help             \$               Install smoke alarm: 1st flr.             n/a             Yes             X             Self Help             \$               Install smoke alarm: 2nd flr.             n/a              X             Yes             Self Help             \$               Repair/replace defective             n/a             X             Yes             Self Help             \$               Repair defective             n/a             X             Yes             Several need new coverings             \$               Ot	350.00	\$	Several cracked glass	s X	n/a	Replace broken glass	
Repair or replace doors	750.00	\$	Several new needed	s X	n/a	Repair or replace sash	_
Walls/Ceilings           Repair or repl. @ defective         n/a	500.00	\$	Several new needed	s X	n/a	Repair or replace doors	Doors
Repair or repl. @ defective		\$	Self Help	s	n/a X		
Paint  Repair or repl. @ defective					. —	_	Walls/Ceiling
Repair or repl. @ defective		\$		s	n/a [χ]	Repair or repl. @ defective	
Install smoke alarm:bsmt.	650.00	\$	Several rooms need fresh paint	s V	n/a 🔲	Repair or repl. @ defective	Paint
Install smoke alarm:bsmt.		Ψ	Covoral recine need need paint	.o [X]	174	rtopan or roph g dolocavo	
Install smoke alarm: 2nd flr.	75.00	\$	Self Help	s X	n/a	Install smoke alarm:bsmt.	Fire Safety
Repair/replace defective	75.00	\$	Self Help	s X	n/a	Install smoke alarm: 1st flr.	
Repair/replace defective		\$	Self Help	s 🗌	n/a X	Install smoke alarm: 2nd flr.	
Repair defective		\$		s 🗌	n/a X	Repair/replace defective	Handrails
Floors  Repair defective  n/a Yes X Several need new coverings  \$ Other  n/a Yes X Basement evidence of MOLD like substance  n/a Yes   n/a Yes   n/a Yes   s  n/a Yes   s  n/a Yes   s		\$		s $\square$	n/a 🔯	Repair defective	Stairs
Other    n/a   Yes   X   Basement evidence of MOLD like substance   \$   n/a   Yes     \$   n/a   Yes   \$   n/a   Yes   \$   n/a   Yes   \$   s   s   s   s   \$   s   s   s   s   \$   s   s   s   s   s   \$   s   s   s   s   s   s   s   s   s   s		*			111 [7]		Floors
n/a Yes X Basement evidence of MOLD like substance \$  n/a Yes \$  n/a Yes \$  n/a Yes \$  n/a Yes \$  s	1,500.00	\$	Several need new coverings	s X	n/a	Repair defective	
n/a Yes \$  n/a Yes \$  n/a Yes \$  1 Yes \$  1 Yes \$  2 Second Secon	1,300.00	¢.	Pagament avidance of MOLD like autotopes	. V	n/o		Other
n/a Yes \$ n/a Yes \$	1,300.00	<b></b>	Basement evidence of MOLD like substance	s X	n/a	-	
n/a Yes \$		\$		s	n/a		
		\$		s 🗌	n/a		
Interior: Estimated Cost: \$		\$		s 🗌	n/a		
	10,100.00	\$	Interior: Estimated Cost:				
Total Exterior and Interior Cost:* \$	14,450.00	\$	Total Exterior and Interior Cost:*				

Prepared by: Jeff Moser, Advantage Home Inspection Services Date: 9/9/2010

## **Self Help**

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

## **Important Information Regarding Permits**

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway. If you will be occupying the home, you can get free lead-safe training from the Health Department! Call 286-5119 to schedule on-site training.

<sup>\*</sup>average contracted cost. Actual costs may vary. Self help will reduce the amount.